

Customer: Coyland

F.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 S&W

GENERAL CONDITION: NEW R # : 24701

OUTSIDE WORK: NO DATE: 12-9-71

FROM: G.H. Sports Co.

FIRED AMMO TYPE: - REM-UMC, Cal.

& CONDITION: \_\_\_\_\_ GUN # : 6300415

PROOF: S&W-E INSP.: 9 TEST: 49 CODE: PT = 5/100

HEADING: O.K. G.K./CAL.: 3008 Cal.

BREECH OPENING: - CHECKED BY: S. PROBERT

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: O.K. APPROVED: \_\_\_\_\_

TEST: NO APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

NO DAMAGED-BROKEN COMPONENTS.

TRIGGER CONNECTOR CLEARANCE 1.068 (M/D = 1.079) TRIGGER

CLEARANCE 1.092 (M/D = 1.085) ENGAGEMENT .020

TRIGGER PULL O.K. SLIGHT CORNER BREAKDOWN ON

SEAR & TRIGGER CONNECTOR CORNERS.

COMPLAINT: FIRES WHEN SAFE IS RELEASED.

INCIDENT: FOLLOWS DOWN

COMMENTS: CUSTOMER'S MALFUNCTION NOT CONFIRMED. IT IS

POSSIBLE WITH COMPONENTS SUCH AS THIS BUILT FOR THE

TRIGGER CONNECTOR TO WORK UP ON THE TRIGGER (CLEAR-

ANCE .017 OVER MAY). ALSO TRIGGER MAY HAVE FAILED TO

RETRACT DUE TO BIND IN THE TRIGGER GUARD CAUSED BY

OUT OF POSITION SCREW HOLES IN THE STOCK.