

RECEIVING AND ESTIMATING REPORT 1

INITIAL LCS		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 09/17/90	DATE OPENED 09/27/90	DATE CODE DQ 9-78	SERIAL NUMBER A6181785	MODEL AND GRADE 788 22-250		ORDER R 90-249	
ACCESSORIES L/CLIP W/STUDS L/ REAR SIGHT							

FROM: G & M GUNS RT 1 BOX 312A MOIRA NY 12957	SHIP TO: G & M GUNS RT 1 BOX 312A MOIRA NY 12957
---	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED 10-3-90	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------------------------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST *Gun goes off when taking safe off.*

MAIN FAULT *Tugpin assembly has been removed from action after leaving factory. It appears that improper re-installation of assembly has resulted in damage to main spring. It appears such alterations may have been made to assembly after leaving factory.*

PARTS *Send repair quotation as requested. Requester to good-will quote 1/2 normal charge.*

REPAIRMAN <i>RBS</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.