

Donald F. Garrison
600 West Dixie St. 79735 8-3-1993
Fort Stockton Texas

Remington Model 700 Cal. 30-06
BDL SPRG.
Serial # 6421105

This Rifle has a Problem With
the Trigger + safety, especially
after it sits up for a while,
When you work the Bolt you
can't work the safety, and
sometimes it will fire.
The Trigger is real hard.

I would appreciate it if you could
Haul this Rifle Back to me by or
before the 25th of Sept. Because I have
a handicapped ~~Elk~~ Permit to

Hunt. Sept. 29 through Oct. 3.

Thanks Donald F. Garrison
600 W. Dixie
Fort Stockton Tex.

Shipped Everything Except 79735
the Stock.