

# RECEIVING AND ESTIMATING REPORT

ORDER NO.		COMMENTS					
		"B"					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
06/88	07/15/88		A6417602	700 30-06 BDL		R	88-19449
RIES		W/STUDS		SCOPE BASE			

GOLD BUSH SALES  
D/B/A CARNIVAL SPORTS  
2505-7 65TH STREET  
BROOKLYN, NY

11204

SHIP TO:  
GOLD BUSH SALES  
D/B/A CARNIVAL SPORTS  
2505-7 65TH STREET  
BROOKLYN, NY 11204

NUMBER	PROM. DATE	ESTIMATED	VIA
			UPS
ARGE	TAX ST	INSURANCE	UPS
	TAX CITY		PARCEL POST
			TOTAL
			\$

CONDITION:  NEW  SLIGHTLY WORN  VERY WORN  MISUSED  QUOTE

ER'S COMPLAINT  
*Gun fires upon closing bolt on loaded rounds,  
no when safety is taken off.*

JLT  
*Testing revealed no malfunctions, however, over-travel  
is found to be set improperly and, trigger return spring  
is binding.*

*Replace trigger assembly of 20-  
shary with new bolt lock  
assembly.*

*7/27/88  
JLB*

COMPUTER REF. ONLY		PROOF
		(CLEAN) (TEST) (TARGET)
		REPAIRMAN
		<i>JLB</i>

OFFICE COPY