

FROM

SHIP
TO:

CONTENTS-MERCHANDISE-
POSTMASTER:
IF NOT DELIVERED IN 15 DAYS
RETURN TO SENDER.

OUR ORDER NO.
177497
09-25-91
DATE SHIPPED

INVOICE •
TO:

REMINGTON ARMS COMPANY, INC.,
ARMS SERVICE DIVISION
14 HOFFLER AVENUE
ILION, NY 13357

SHIP TO:

GUN CORRAL, THE
2827 E COLLEGE AVE.
TWIN OAKS SHOP CTR.
DECATUR
USA 3

GA

30030

PROM. DATE 10/10/64	ESTIMATED	VIA UFS
------------------------	-----------	------------

WARRANTY REPAIR STATION

100-0000033 EC-BH

We are sending you this gun on behalf of our customer S. Stroud. The complaint is that the gun is going off while on safety or while being pushed off to fire. We worked on this gun on 10-25-90 (our #5440) in which we found the gun very dirty and greasy with the only problems being a bind in the cocking piece and rough threads in the firing pin mech. Our customer is very afraid of this gun and wants it inspected and completely tested (it has AD's three times total. Please repair as needed under WARRANTY and return to us as soon as possible. THANK YOU!!

Thirion

5	PARCEL POST	TOTAL
WORN	☐ MISUSED	☐ MARRED

or while being pushed off
However, it was noted the
out and safety force is too low.
assembly is wet with
all 5 pounds; sea lift. or

Offer new design assembly at
nominal cost, as a gesture of
goodwill, based on condition of film
assembly.

ARTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 R: