

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER NO. 92-13568	
INITIAL		CUSTOMER ORDER NO.					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
06/19/92	06/22/92	DJ 9-89	C6442980		700 7MM MAG AS		
ACCESSORIES		SCOPE BASE					
W/STUDS							
FROM: GUNROD, DAVID 143 NORTH PENNOCK UPPER DARBY PA 19082				SHIP TO: GUNROD, DAVID 143 NORTH PENNOCK UPPER DARBY PA 19082			
CUST NO: 062635 C.D.D.							
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS	
					7-7		
GUN CONDITION				REPAIR CHARGE			
☒ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ REPAIRABLE ☐ DAMAGED				☐ EXCISE ☐ TAX ☐ INSURANCE ☐ UPS ☐ PARCEL POST ☐ TOTAL			
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE		B1					
TRIGGER GROUP		B2					
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT: 1) Unable to duplicate complaint - trigger assembly operates properly - even against trigger pull - 5 pounds. Rear lift - 12" 2) Front end of trigger assembly still in chamber 3) Hook is jammed through gun screw hole from front to back							
PARTS				COMMENTS			
				1) Remove stuck cam from chamber			
				2) Have stock checked for abuse (Was it not?)			
				3) Offer to replace trigger at \$200.00 as gun is good - will, if we can site rifle with present trigger assembly			
REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTER	
BWT							
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

R06925 REV. 1/