

Cast Camp

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL.

GENERAL CONDITION: NEW R # : 26180

OUTSIDE WORK: SCOPE MOUNTED, REGULAR DATE: 12-21-71

SIGHTS REMOVED. FROM: H. H. SOTA, GDS, INC.

FIRE AMMO TYPE: R.P. AMARILLO, TEXAS.

& CONDITION: ONE PIERCED PRIMER GUN # : 6334559

PROOF: R.E.P.-B INSP.: 71 TEST: 49 CODE: CT= 4/70

HEADING: O.K. GA./CAL.: 25-06 B.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: TEN ROUNDS OF 120 GR. - NO PIERCED APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) PRIMERS, APPROVED: _____

FIRING PIN POINT TOO FLAT. TRIGGER CONNECTOR

DAMAGED. SEAR-TRIGGER CONNECTOR ENGAGEMENT

.005

COMPLAINT: RIFLE WILL NOT COCK.

INCIDENT: FOLLOWS DOWN.

COMMENTS: THE .010 UNDER MIN. ENGAGEMENT COMBINED WITH

BACKLASH FROM PIERCING PRIMERS BROKE DOWN

THE CORNER OF THE TRIGGER CONNECTOR RESULTING

IN THE FOLLOW DOWN MALFUNCTION.