The



## REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

## ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

October 2, 1989

Mr. Omar Hallum 126 Byron Victoria, TX 77901

Dear Mr. Hallum:

•

Your letter of August 21, 1989, concerning the problems you have experienced with your Remington Model 700 rifle, "on three occasions my Remington 700 has fired when I released the safety," has been referred to this office for handling.

We were indeed sorry to learn of your having problems of the nature you described.

Remington would appreciate the opportunity to examine your rifle to try to determine the cause of the accidental discharges you encountered. To this end, we request that you forward the rifle along with a description of the use of it both before and after the incidents you experienced, via U.P.S. transportation C.O.D. to:

Remington Arms Co., Inc. Attn: J.A. Stekl, Product Service 14 Hoefler Ave. Ilion, Ny 13357

Please boidly mark the two (2) butt ends of the outside of the package "STEKL" to expedite handling.

We will immediately notify you of our findings upon completion of our examination.

PPS 02151