

Cost Comp

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 021210
OUTSIDE WORK: No DATE: 10-20-72
FROM: HALSTEAD'S
HOUSTON GARDEN
SUMMERVILLE, N.H.
FIRED AMMO TYPE: - GUN #: 6381922
& CONDITION: _____ CODE: ET = 10/10, PH2 = 4
PROOF: P.F.P.-C INSP.: 58, 97 TEST: 98 GA./CAL.: 300 WLL MAG.
HEADING: O.K. CHECKED BY: C. PROCTOR
BREECH OPENING: - APPROVED: _____
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER ASSEMBLY CORRECTLY SEALED BUT APPEARS
NEVER TO HAVE BEEN ADJUSTED.

COMPLAINT: DISCHARGED THREE TIMES WITHOUT FINGER ON
TRIGGER.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE EXCESSIVE TRIGGER MOVEMENT ALLOWED
THE CONNECTOR TO CATCH ON THE STOP SCREW AND
FAIL TO RETRACT CAUSING FOLLOW DOWN.