

Jim

This was
poorly packaged
The stock
broken

John

Jim:

WE COULD FIND NO REASON FOR
THE CASE SEPARATION - AND I
CAN'T FIND ANYTHING OBVIOUSLY
WRONG WITH THE GUN - THE CASE
SEPARATED AHEAD OF THE EXTRACTOR
GROOVE.

THE OLD GAL SOUNDS PRETTY
NICE BUT MAY HAVE A WORN
OUT GUN

Bill

78643

Dear Mrs. Harlow:

We have our ballistics report on the 222 Rem mag cartridges you
returned for examination.

The unfired rounds were fired in our ballistics laboratory and
tested for velocity. The cartridges performed satisfactorily. The
velocity was slightly low but the rounds are 15 years and may have
deteriorated slightly since they left our plant.

The cartridge that separated when you fired it was examined by our
metallurgist and no metal defects were found.

Based on these tests we have been unable to duplicate the problem
which you experienced or to find a cause for it. Accordingly, we
have shipped your rifle to our firearms plant in Ilion, NY, for
examination by our firearms experts. You will hear directly from a
technician at that plant as soon as the examination has been
completed.

In the meantime, to compensate for the product returned for our
tests, please find enclosed a check for \$26.00 to cover the cost of
two boxes of 222 Rem Mag cartridges.

We hope this is satisfactory and please advise if we can be of any
further service. Again, you will hear shortly from Ilion regarding
your rifle.

Cordially yours,

W. T. Smith

W. T. Smith, Supervisor
Product Service

WTS:vn

bcc: Jim Stekl