

SHOP REPAIR ORDER

3274

PARTS DESCRIPTION	LABOR	PAINT	AMOUNT
Steering Wheel Ring	0.5		20 20
Left Door Panel	0.3		32 82
Windshield	2.5		28 00
Steering Wheel Knob	0.3		4 25
Front Fog & Door	0.2		13 48
Wire Room Left	—	—	—
Side Compartment	5.0		679 70
Emission Control	—	—	—
Box	0.2		113 80
Right Surtel	0.3		32 28
	9.3		104 93
Open Items / Sublet			
Leas Seat Buck			
or Complete Seat			
120 Hatch			

estimate

CUSTOM PAINT & BODY, INC.

209 S. Fairview Avenue
FARMINGTON, NEW MEXICO 87401
(505) 327-3088

CLAIM #

000-928-002-01-01-019

Name Philip Noyard

Date 4-24-84

Address 5205 Fargo St

City Farmington

Home Phone 327-7814

Business Phone

Year 81

Model Toyota

Color Red

Engine 20580

Trans 34

REP.

INSTRUCTIONS 5-81

LABOR

PAINT

Front End Panel
Left Side Panel
Left Door
Right Side Panel
Fire Wall

"Accounts not paid within thirty (30) days of the date repairs are completed will be charged interest at the rate of 1-1/2% per month, in the event an attorney is employed by Custom Paint & Body, Inc. to collect a past due account, it is agreed that such attorneys fees will be reimbursed to Custom Paint & Body, Inc. by the customer."

The above is an estimate based on our inspection and does not cover any additional parts or labor which may be required after the work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change.

AUTHORIZATION FOR REPAIR. You are hereby authorized to make the above repairs:

SIGNED

TE

PARTS Prices subject to invoice

LABOR \$ 1900

PAINT \$ 1900

PAINT SUPPLIES \$

SHOP SUPPLIES \$

TOWING/STORAGE \$

FRAME \$

SUBLET \$

MISC. \$

SUB TOTAL \$

TAX \$

TOTAL \$

Received AM PM
Promised AM PM
Ins. Co. GEICO
1800 841-3000
Adjuster
Speedometer

30

119493

31920

5700

3000

10500

160573

1237

21641