

AND

Enclosed is a 700 BDL. Customer says
rifle will fire when Bolt closes. and
also when ~~top~~ trigger is pulled, a delay
happens before gun fires. Please repair

R

9073

Thank you.

HENRY'S GUNS "R" US
5450 Main Street
Mt. Jackson, VA 22842
(703) 477-3447

2017

2017