

RECEIVING AND ESTIMATING REPORT

INITIAL RLP		CUSTOMER ORDER NO.		COMMENTS <i>Stake</i>	
DATE RECEIVED 09/12/90	DATE OPENED 09/24/90	DATE CODE AB 3-B1	SERIAL NUMBER B6317109	MODEL AND GRADE 700 25-06	ORDER R -90-2
ACCESSORIES W/STUDS SCOPE BASE L/ REAR SIGHT					

FROM:	SHIP TO:
HENRY'S GUNS "R" US RT 11 N MAIN ST RT 1 BOX 442 MT JACKSON VA 22842	HENRY'S GUNS "R" US RT 11 N MAIN ST RT 1 BOX 442 MT JACKSON VA 22842

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *"the rifle will go off prematurely. It has gone off on 2 occasions with safety on."*

MAIN FAULT *Cannot duplicate complaint - it is mechanically impossible for this rifle to fire with the safety on. Trigger assembly has been improperly adjusted out of factory. Trigger pull is below spec. at 2 1/2 # and over-travel is insufficient. Sear lift measured to be .014"*

PARTS *Either (1) re-adjust present trigger assembly to proper specification of possible or (2) send gun back for new trigger assembly at ± normal price as gesture of good-will.
Rifle is 9 years old.*

REPAIRMAN <i>Stake</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.