

Enclosed is a Rem 700 BDL
in 25-06. cal. The rifle will
go off pre-maturely. It has
gone off on 2 occasions with
Safety on. Please repair
I need gun back by Nov. 1st

4559

Thank you.

HENRY'S GUNS "R" US
Route 11, N. Main Street
Route 1, Box 442
Mt. Jackson, VA 22842
(703) 477-3447

2 anxious with safety on 1 0 10

- 1) Cannot duplicate complaint - it is mechanically
possible for this rifle to fire with the safety on.
2) gun evidently has been improperly adjusted out of factory
3) you pull to below spec. at 2 1/2" and good-travel is insufficient
4) weight measured to be .014"

Either (1) re-adjust present trigger
assembly to proper specification of
possible or (2) send gun to factory for new
trigger assembly at $\pm$ normal price,
as gesture of good-will.

Rifle is 9 years old.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 6/88