

R 94-16301

CUSTOMER ORDER NO.

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
05/19/94	05/20/94	EH 10-92	S6217973		700 33B WIN MAG/ADL/SS
ACCESSORIES	W/STUDS				

OK
73044

UFS

TOTAL	100	100
-------	-----	-----

MAIN FAULT May 10-92 Unable to duplicate customer's concern as noted. Trigger
pounds, pull and overtravel seems have been altered outside of
the factory. We do not recommend that the trigger be adjusted
outside of the factory. Exchange trigger for \$59.95 at a
special price simply as a gesture of good will.

[illegible]

RD6925 REV. 1/94