

RECEIVING AND ESTIMATING REPORT ✓

CUSTOMER ORDER NO.		COMMENTS WOG 2 OF 2 W/FRONT SCOPE BASE ONLY	
DATE RECEIVED 7/22/91	DATE OPENED 01/29/91	DATE CODE OK3 7-63	SERIAL NUMBER 6241200
MODEL AND GRADE 700 243 BDL		ORDER R 91-02994	
ACCESSORIES W/STUDS			

TO:	SHIP TO:
HOPSON, DAVID L 11446 LOYOLA CYPRESS TX 77429	HOPSON, DAVID L 11446 LOYOLA CYPRESS TX 77429
COUNT NUMBER	ACCOUNT NUMBER N/C
WRITE ☐	CLEAN/TEST
PROM. DATE	ESTIMATED
VIA UPS	

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☒ MISUSED ☐ MARRED

COMER'S REQUEST: *"... will fire while chambering the shell."*

NO FAULT: *As received firing pin will follow down as fast as closed sometimes. Trigger assembly is contaminated with gummy, sticky deposit. See safety cam sticks to side plates of trigger housing. Bolt stop is inoperative, tending to occur; floor plate release is inoperative. This rifle has been very poorly maintained.*

Clean present trigger assembly (and action) if possible - if not, send quotation for new trigger assembly for 1/2 normal cost, as gesture of good-will. When rifle is sent back, include a copy of my/ro Brown's Manual for instruction on proper maintenance

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90