

MR STEKL

Thank you for reporting the finding to me. I understand the position that Remington is in and even though the gun was put through all the necessary test, and passed them all, but I am sorry but I have to disagree with the finding. Please don't take the wrong, but I still feel that because the gun was basically inside the case, nothing could have hit the trigger. After discussion with gun salesman, and a Idaho Fish & Game officer, I have found out that they have had instance when their Remington firearm has fired when they moved the safety switch from "SAFE" to "FIRE". I feel that the incident was a freak accident, and through the incident I was able to learn a cheap lesson. I am perfectly content to have the "original" trigger assembly replaced in the gun. I am a consistent buyer of Remington products, guns and ammunition, and even though Remington was not able to find anything mechanically wrong with the gun, I do hope that Remington will be able to replace the damaged Remington case with one of the same model & style. Again thank you and you can bet that next winter I'll be back outside when the weather will my 22-250.

REC-1

FEB 4 1960

J.A. STEKL

Thank You
Lewie Huddleston Jr.