

CUSTOMER ORDER NO.		COMMENTS ST JOHN	
RECEIVED 14/88	DATE OPENED 11/21/88	DATE CODE BB 1-81	SERIAL NUMBER A6833231
MODEL AND GRADE 700 30-06 BDL		ORDER R 88-31071	
SERIES SLING STRAP W/STUDS		W/SWIVELS	

A: JAMES HUFFORD 13 LAKEWOOD LN. PINE BLUFF, AR. 71603	SHIP TO: JAMES HUFFORD 13 LAKEWOOD LN. PINE BLUFF, AR. 71603
--	---

JNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA V019642446
------------	--------------------	--------------------------------	------------	-----------	-------------------

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

OWNER'S REQUEST

"Rifle has been known to malfunction at very unexpected times".

FAULT

*thorn of action and trigger loaded with excessive lubrication. Bolt stop
and bear safety cam move very sluggishly - much of trigger
assembly also contains excess lubrication accumulation.*

- 1) Clean excess oil off action*
- 2) Install new bolt-lock safety
trigger assembly at no charge.*
- 3) expedite return of rifle to owner.*

*11/28/88
JES*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD0923 REV. 6/88