

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-06101

INITIAL JJM	CUSTOMER ORDER NO.	DATE RECEIVED 02/19/92	DATE OPENED 02/26/92	DATE CODE PJ 6-89	SERIAL NUMBER C6396656	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	ADL
ACCESSORIES SCOPE BASE W/STUDS								

FROM:

HUGHES, GARY R
400 THOMAS RD
PAULINE

SC 29374

SHIP TO:

HUGHES, GARY R
400 THOMAS RD
PAULINESC
29374

CUST NO: 058726 CJO.D

ACCOUNT NUMBER	ACCOUNT NUMBER NC	WRITE ☐	CLEAN/TEST	FROM DATE	ESTIMATED	VIA UPS
----------------	-------------------	--------------------------------	------------	-----------	-----------	------------

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
YCLE	A1	B1				
RIGGER GROUP						
OLT ASSY.		B3				
ARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
'OOD'			C1	D3	E5	F5
ETAL			C2			

GUN FAULT

As received, rifle would not function. Inspection revealed that trigger assembly was contaminated with a gummy residue - the cam safety arm was stuck to the side plate of the trigger assembly and would not move.

RTS

COMMENTS

Offer new trigger assembly at normal cost, our gesture of good-will.

REPAIRMAN BET	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RECEIVED DEL 001

PPS 02480