

RECEIVING AND ESTIMATING REPORT

R93-09752

CUSTOMER ORDER NO. L46035					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
2/93	04/13/93		A6663447		700 7MM MAG BDL/LH
ORIGES W/STUDS		SCOPE BASE		L/SIGHTS	

SHIP TO:

JAY'S SPORTS
N 88 W 15263 MAIN ST
MENOMONEE FALLS

WI 53051

JAY'S SPORTS
N 88 W 15263 MAIN ST
MENOMONEE FALLS WI
53051

CUST NO: 007266 ILION

NT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
CONDITION	REPAIR CHARGE EXCISE 85.00 TAX INSURANCE UPS PARCEL POST TOTAL				
N					
HTLY WORN					
RN					
Y WORN					
REPAIRABLE					
RED					

OWNER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
	A1	B1				
ER GROUP		B2				F1
SSY.		B3			E2	F2
L ASSY.		B4		D1	E3	F3
SSY.		B5		D2	E4	F4
			C1	D3	E5	F5
			C2			

ULT Upon receipt of rifle, ammunition revealed firing pin of trigger
has been badly bent down and removed. The end of the trigger
that the inside of the trigger found bent. All parts removed.
Inspected for bent trigger. The firing pin was bent, the firing pin was bent,
this will affect the trigger. (See picture of ammunition, note attached)

COMMENTS

Revised trigger assembly complete at
1/2 normal replacement cost.

Go ahead - OK per Jgt 5/10/94

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5925 REV. 1/92