

BDC - two WASHERS, ONE FRONT.
" REAR.

EXAMINATION OF TRIGGER:
CONTACTS BOW WHEN
PULLED, DUE TO BEND

ALTERATION OF TRIGGER
FINGERPIECE.

TRIGGER pull WITH
TRIGGER BOW REMOVED:

4.52

4.60

4.44

4.58

4.46

=> Lots of drag
on trigger due to
Bow !!