

RECEIVED

JAN 31 1989

RECEIVED

JAN 25 1989

R.B. SPERLING

CONSUMER SERVICE  
1-16-89

Dear Sir - To whom it may concern  
I am the owner of a Remington  
model 700 ADL Bolt Action 308  
Caliber Rifle that I purchased  
on date of 10-8-1984. Serial number  
is B6483050.

During Deer season in November  
of 1984 it misfired once when  
I closed the bolt loading another  
shell in the barrel. It fired  
just as I got the bolt closed and  
before I had the chance to  
push the safety lever into  
safety position. I know you  
published a recall article in  
the paper about a year ago  
on some that were defective  
but I was informed that they  
were later models than mine.  
I'm very concerned again  
now after reading a article