

24704



REMINGTON GUN AND/OR TRAP REPAIR INVOICE

 REMINGTON ARMS CO., INC.
 ILION, NY 13357

Remington Recommended Repair Facility

 Name Kendall's Gunsmithing, Inc. 2144
 Street 927 JEFFERSON AVE
 City WASH State PA Zip 15301

 Customer's Name Kenneth Hall
 Street 239 Penn Cornhill St
 City Pennville State PA Zip 15431

Date Firearm or Trap Received		Date Returned to Customer		Returned to Factory	
				Date	Via
11-10-90		11-10-90			
Gun Model 706	Cal. or Gauge 7.62mm	Grade BVA	Barrel Code -PH	Serial Number 12541721	
Trap Model Trap ☐ Skeet ☐	Counter #	Serial Number			

Complete Description of Customer's Complaint

RIFLE FIRES WHEN SAFETY IS ROTATED TO FIRE POSIT.

Repairs Performed—Describe in detail

MAJOR FAULT: TRIGGER DID NOT RETURN
 TO RESET POSITION AFTER BEING PULLED
 THERE IS VISIBLE EVIDENCE OF RUST ON TRIGGER
 MECH. WE FEEL THIS WAS THE PROBLEM WE ARE
 SENDING THE DEFECTIVE TRIGGER MECH TO THE
 ATTENTION OF MR. GAIL L. HALL TO BE
 EXAMINED BY YOUR TECHNICIAN
 WE FIT A NEW TRIGGER MECH & PERFORMED ALL
 NECESSARY TRIGGER T. T. ADJUSTS

Repair Charge Breakdown

Parts	\$ 42.48
Labor	12.50
Test Ammunition	
Testing Targets	
Packing	
Transportation	
Total	\$ 54.98

GUNSMITH FILE COPY

 Arms Service (2)
 REMINGTON ARMS CO., INC.
 ILION, NY 13357

 Date: 11-10-90