

P.I. YPS GUN EXAMINATION REPORT NUMBER: 701

MODEL: 600

GENERAL CONDITION: POOR

R # : 13881

OUTSIDE WORK: STOCK DRILLED FOR STADS

DATE: 9-13-82

STADS. SCOPE MOUNT ADDED

FROM: HOLLYWOOD KLEIN

FIRE AMMO TYPE: NOT KNOWN

SEY 277-118 TV

& CONDITION: _____

GUN # : 92537

PROOF: REP INSP.: 73 TEST: 18

CODE: PP-6-67

HEADING: OK

GA./CAL.: 644 REP

BREACH OPENING: OK

CHECKED BY: M-DEAD

RECOIL SHOULDERS: OK

APPROVED: COM 8/31/82

CHAMBER: APPEARS OK

APPROVED: SEA 5/31/82

TEST: _____

APPROVED: SEA 2/1/82

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: SEA 3/31/82

DIRTY USED STOCK MOUNTED RECOIL MOUNT

RECALL FIRE CONTROL HAS BEEN 1 TALE

COMPLAINT: FIRED WHEN SECTY WAS MOVED TO
OFF POSITION

INCIDENT: _____

COMMENTS: Unable to duplicate customer complaint. Gun
appears to be normal in every respect.

• OK in Trick Test

• Saw lift .0115" in Null position

• Saw lift .013" full scale

• Trigger Pull 4 1/2 lb

Return gun to E. Sienkiewicz per his letter