

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R91-23325

INITIAL

CUSTOMER ORDER NO.

FPS

RV51617

DATE RECEIVED
11/12/91DATE OPENED
11/15/91DATE CODE
DI 9-88SERIAL NUMBER
C6303917

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

LH BDL

ACCESSORIES

W/STUDS

FROM:

L.L.BEAN
ACCOUNTING DEPT
CASCO ST
FREEPORT
USA

ME 04033

CUST NO:033352 ILION

SHIP TO:

L.L.BEAN
RETAIL STORE
MORSE ST
FREEPORT
USAME
04033

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

1) The bolt release button sticks & allows the bolt to drop out when it should not

2) The trigger assembly has discharged twice when the safety was pushed off

MAIN FAULT

Trigger assembly has reacted from unknown source - internal trigger parts not moving freely nor properly

PARTS

COMMENTS

1) repair bolt stop

2) replace trigger assembly at A/C as gesture of good-will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTEF

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8

PPS 02856