

RECEIVED

AUG 19 1986

Dear Sir
R.H. POTIER

RECEIVED

AUG 19 1986

ARMS SERVICE

8-14-86

I own a Remington 700 S/N A6412209, which was purchased APPROX eight years AGO. Two years AGO while sighting in my rifle and while inserting a live shell into the chamber, with the bolt, the rifle discharged. Rifle was taken to a local gunsmith and no problems were found.

Last year, while deer hunting I was unloading my rifle, shells were removed from the magazine and when I lifted up on the bolt to remove the round in the chamber the gun went off and the bolt drove to the rear.

My rifle is in excellent condition and has fired approximately 50 rounds since purchase, however I am frightened this may happen again.

I have taken it to a certified gunsmith and nothing wrong has been found. I feel something is wrong with the action on this rifle for it to do