

SHOOTING AND ESTIMATING REPORT

COMMENTS

ORDER
R 73-25471

CUSTOMER ORDER NO.

ATTN: D J SANITA

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
9/93	12/01/93	EJ 10-89	C6462090		700 270 ADL
W/STUDS			SCOPE BASE		

SHIP TO:

LESTER, CHARLES
120 JUANITA AVE
WILLS POINT

TX 75169

LESTER, CHARLES
120 JUANITA AVE
WILLS POINT

TX
75169

CUST NO: 087882 C.O.

NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA
	059015			
WRITE	☐	8631197859		
CONDITION	UP5 2nd day Cin			
LY WORN	REPAIR CHARGE			
WORN	EXCISE			
PAIRABLE	TAX			
ED	INSURANCE			
	UPS			
	PARCEL POST			
	TOTAL			

CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
GROUP	A1	B1			E1	
SY.		B2			E2	F2
ASSY.		B3			E3	F3
SY.		B5	D2		E4	F4
					E5	F5

Wrote to duplicate customer concern. Right function as required.
Trigger pull - 5 1/2 lbs
Semi lift - .015
Determined that the shot is caused at the magazine level

COMMENTS

Repaired trigger assembly & checked action. as before & good used to help with fault in rifle

Ship back in rifle had case
Go ahead per phone 12/1/93 with Mr. Sanita

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE		