

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORD
R 93-133INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
06/08/93DATE OPENED
06/09/93DATE CODE
AK 3-63SERIAL NUMBER
59982

NEW SERIAL NUMBER

MODEL AND GRADE
700 222

ADL

ACCESSORIES

SCOPE BASE

FROM:

LIVINGSTON, RICHARD M
4010 PEAKLAND PL
LYNCHBURG

VA 24503

SHIP TO:

LIVINGSTON, RICHARD M
4010 PEAKLAND PL
LYNCHBURG

24503

CUST NO: 079348 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

7-9-93

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE ☒

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	*INSPECT
CYCLE	A	Was unable to get rifle off safe - manipulated for			E1	F1
TRIGGER GROUP		+ safety then			E2	F2
BOLT ASSY.		Can will fire when closing Bolt			E3	F3
BARREL ASSY.	B4 B5			D2	E4	F4
REC. ASSY.				D3	E5	F5
WOOD			C1			
METAL			C2			

MAIN FAULT

Rifle mfg. 1963
Upon receipt rifle would not function (would not fire). Upon
inspected that the trigger assembly has had the safety removed
from the adjustment screw. Inspecting it has been tampered
with.

Replace complete trigger assembly
Check firing pin assembly
at 4x normal replacement
cost go ahead

REPAIRMAN
RBS

PROOF

CLEAN ☒TEST ☒

TARGET

GALLERY TESTER

DATE

DATE

DATE

DATE

OFFICE COPY

RD6