

Loudon County Sportsman

1/31/94

M/788-22-250 Ser # A-6152748

^{Complaint}
^{Fault Found} When you close the bolt the gun will go off
Gun will follow down intermittently when the
bolt is slammed closed.

Trigger pull measured between $\frac{1}{2}$ and $\frac{3}{4}$ lbs
checked 5 times

Removed H. aug. Action stuck in stack due to
glass bedding

Firing pin striker has been stoned or polished

Disassembled trigger:

Sear spring shortened ~~to~~ from approx. 300
Sear polished/stoned reducing sear
engagement

[Signature]

INTER

ATE

REV. 1/92