

After this happened twice I had the gun checked by Mr. Percy Summers a local gun smith. I hunted a Few days later with no problems Firing the gun twice. Two days later the sequence described earlier happened again. It doesn't happen with every use of the gun and is unpredictable.

I am a veteran hunter and experienced with Fire arms so please don't pass this off as a case of Buck Fever or carelessness.

I have two Friends who purchased identical guns the same day as I purchased this one. Neither of them have experienced this problem, however they eagerly await your Response as I do.

IF there is any expense on my part I request prior approval before the repairs are made.

I can be Reached during the day at 1-502-247-5665 and Nights at 1-502-382-2699.

Sincerely

Robeth. Crandall

P.S. IF Repairs are made on the gun I would like to know in detail what they were as I have to decide what to do with this gun. I Feel justified in this case in asking you to Replace this with a new gun.