

McBRIDES INC.

30TH AT N. LAMAR • AUSTIN, TEXAS 78705 • (512) 472-3532

MESSAGE

REPLY

Remington Arms Service

I Lion, N.Y. 13357

10/21/93

We are sending the enclosed
Model 721 #176510 for a customer
who indicates —

- (1) Trigger is too light — Sometimes Gun
goes off when bolt is closed.
- (2) please check for proper function.

[Signature]

DATE

BY
Item # NR73 The Drawing Board, Dallas, Texas 75266-0429
© Wheeler Group, Inc., 1982

INSTRUCTIONS TO SENDER:

1. KEEP YELLOW COPY. 2. SEND WHITE AND PINK COPIES INTACT.

SIGNED

INSTRUCTIONS TO RECEIVER:

1. WRITE REPLY. 2. DETACH STUB, KEEP PINK COPY, RETURN WHITE COPY TO SENDER.

5-2634

(5) WHS

REPAIRMAN	PROOF	DATE
GALLERMASTER	DATE	

OFFICE COPY