

MGBRIDES INC.

30TH AT N. LAMAR • AUSTIN, TEXAS 78705 • (512) 472-3532

MESSAGE

REPLY

TO

Remington Arms
Attn: Product Service

DATE

TE

2-3-92

Gentlemen:

The enclosed 700ADL
243 ser# 37804 needs repair.
Customer said gun goes off when
losing. Customer said gun was
out back to you 15 yrs ago for
same problem. Please correct &
return for return to customer.
Your promptness & attention
is appreciated. Thank You

SIGNED

MGBrides

n • NR73 The Drawing Board, Dallas, Texas 75266-0429
Wheeler Group, Inc., 1982

INSTRUCTIONS TO SENDER:

1. KEEP YELLOW COPY. 2. SEND WHITE AND PINK COPIES INTACT

INSTRUCTIONS TO RECEIVER:

WRITE REPLY. 2. DETACH STUB. KEEP PINK COPY. RETURN WHITE COPY TO SENDER.