

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 93-23584

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

10/29/93

11/02/93

CV 4-79

A674600B

700 6MM

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH ON LAMAR

AUSTIN

TX 78705

SHIP TO:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH ON LAMAR

AUSTIN

TX

78705

CUST NO: 006578 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

11-29-83

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

REPAIR CHARGE

25.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

is sometimes goes off when bolt
is closed
B3
B4
B5
C1
C2
D1
D2
D3
E1
E2
E3
E4
E5
F1
F2
F3
F4
F5

MAIN FAULT - Sent to product service for evaluation

Unable to duplicate customer concern. However, ammunition would a heavy
strike on trigger or action and trigger assembly. Bolt stop action has no return
movement. Bolt has been seen pop out
Numerous marks 11/14/93

PARTS

COMMENTS

Updon trigger trigger assembly
& then action out of normal
updown out, a lot of good work
go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

PPS 03259