

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER

94-12201

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/06/94

04/07/94

DT 7-70

6358541

700

7MM MAG

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

MCCARTY, DARWIN
2303 ASPEN DRIVE
ALAMOGORDO

NM 88310

MCCARTY, DARWIN
2303 ASPEN DRIVE
ALAMOGORDONM
88310

CUST NO: 095516 CLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

* Receiver area and bolt channel are glass bedded.
* other than adjustments, gun has been well maintained and clean

REPAIR CHARGE 1500
EXCISE
TAX
INSURANCE
UPS 8.00
PARCEL POST
TOTAL 23.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

After 7-70 unable to duplicate customer complaint as rec'd. All trigger adjusting screws have been altered from factory setting. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger assy. at a special price strictly as a gesture of good will and to restore customer's confidence in the rifle.

PARTS

COMMENTS

Triggers pull manual 2 1/2 * 3 lbs and break lift was .0075

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 03283