

RECEIVING AND ESTIMATING REPORT ✓

INITIAL LCS		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/06/90	DATE OPENED 12/11/90	DATE CODE AM 3-65	SERIAL NUMBER 134230	MODEL AND GRADE 700 30-06 ADL		ORDER R 90-3224	
ACCESSORIES							

FROM:

MCCRARY, JERRY
PO BOX 235
KODIAK AK 99615

SHIP TO:

MCCRARY, JERRY
PO BOX 235
KODIAK

AK
99615

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA V35111021
----------------	--------------------	--------------------------------	------------	------------	-----------	------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☒ MISUSED ☒ MARRED

CUSTOMER'S REQUEST: *It has been occasionally firing prematurely as the safety is pushed forward or the bolt is lowered to the cocked position*

MAIN FAULT: *Trigger assembly contaminated with gummy residue and rusting; internal parts not moving freely.*

PARTS	<i>Send repair quotation for 1 normal price on replacement bolt-lock safety trigger assembly. Gun in good will, as upl. is 25 years old.</i>					
REPAIRMAN JTB	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

REV. 7/90

PPS 03321