

To Remington Arms:

I purchased this model 700 in .308 caliber some 16 years ago, I believe it was 1977. I bought it at the advice of my cousin, who had one, whom I hunted with at that time. His had a problem, of which I ignored at the time. His would discharge, when moving the safety from Safe to Fire, live load of course. It was intermittent so I began to suspect mine might also have this problem. It was about 1984 when mine discharged, I was not expecting it, though as always had the gun pointed in safe direction. I brought the gun home, never hunted with it again. I called Remington last year, 1992, and discussed it with a representative, of course they wanted to inspect it. So here it is, July 1993, please call or write to inform me what you found, and to what level of comfort I should expect when hunting with it.
(Safety)

Thank You,

P.S. The situation has happen twice, once live, once dry fire.

BILL MEDLIN
1056 Honeycreek Road } OFF.
Conyers, GA. 30208
(404) 760-0410 office
(706) 464-4182 HOME