

December 30, 1993

Remington Arms Company, Inc.
Dennis Sanita
14 Hoefler Avenue
Iliac, New York 13357

Mr. Sanita,

Enclosed is a Remington 700 a customer of mine has recently written to you about.

Mr. Nemec has had problems with this gun discharging when the bolt is closed while chambering a round.


Mr. Nemec also has a second Model 700 that was purchased at the same time as the one above.

He has had no problem with the second Model 700, but wonders if it was included in the recall of these guns that you had a few years ago.

Please send me the range of serial numbers that the recall affected so we can determine if this second gun is involved.

A copy of your letter to Mr. Nemec and a copy of my FFL is enclosed.

Sincerely,



John Miller
FFL # 5-74-178-01-6F-26745