

DECEMBER 26, 1985

MR. L. J. MOORE

P.O. Box 179

FOLLOESVILLE, NC 28573

Dear Mr. Moore:

Your letter of December 12, 1985 that was sent to our Goldsboro, North Carolina facility, concerning the accidental firing you experienced with your Model 700 220 Win caliber rifle, has been received and entered in this office for handling.

We have indeed made a loan to you having a number of the rifles on hand, as it is not representative of Remington-Union City, nor characteristic of the Model 700 rifle.

Generally, the type of incident as described usually occurs with improper adjustment of the trigger assembly, which can be done, from improper maintenance of the rifle, or from inadvertent contact to the trigger.

Please let your insurance, where the rifle was stored, transmission S.O.D. 700.

Respectfully,
Sincerely,
Product Training Division

Product Training Division

Product Training Division

Product Training Division

I am to believe that the name of the rifle of the subject

is the rifle "Still" to be used for training.

Very respectfully,
Product Training Division