

## Moore's Sporting Goods Company

Scopes — Shooting-Things — Binoculars

1-9. 86

Remington Arms Co.  
Ilion, N Y

Mr. J.A. Stekl, Supervisor  
Product Service Division

Dear Sir;

With reference to your letter of Dec 1985;

You received a copy of the transmission repairs which resulted after the gun fired into the flywheel plate. After that time I carried the gun on a deer hunt; was sittin on the front end of my truck and took the safety off when the gun fired with out any contact by me of the trigger.

I carried this gun to an area gun smith and am also sending you his statement. We hunted the rest of our season and had absolutely no further malfunction after he serviced the gun.

Yours truly

*J. Moore*  
L. Moore

Serial Number 6730544  
Remington Model 700 Calibre 270

I have in my collection one 373, one 7.62 two 30,06 ,2 270- 1 6mm  
one 22-250 All Remington- one 22 auto rifle two Rem auto shot guns

I feel the gun is now fixed never the less you said to send it in am  
doing as you said.