

Castro Complaint.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: FAIR R # : 12988

OUTSIDE WORK: SCOPE MOUNTED DATE: 6-28-71

FROM: NAT. PARK SERV.

FIRE AMMO TYPE: - KAHULUI, MAUI, HAWAII

& CONDITION: _____ GUN # : 6258663

PROOF: R.E.P.-E ASSEMBLER 64 INSP.: U TEST: 87 CODE: 05 = 7/69

HEADING: O.K. GA./CAL.: 3006

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS.

CONNECTOR CLEARANCE ON TRIGGER 1.062 M/D = $\frac{1.079}{1.076} - .014$

TRIGGER CLEARANCE ON CONNECTOR 1.087 M/D = $\frac{1.083}{1.080} + .004$

CONNECTOR-SEAR ENGAGEMENT .025-O.K.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.

COMMENTS: CAN NOT DUPLICATE THE CUSTOMER'S MALFUNCTION.
THE TRIGGER CONNECTOR & TRIGGER NOT TO MODEL
DRAWING PERMIT SEAR, CONNECTOR INTERFERENCE,
FAILURE TO RETRACT.