

P.I. YES GUN EXAMINATION REPORT NUMBER: 74 MODEL: 700-LH BDL
GENERAL CONDITION: FAIR R #: 02021
OUTSIDE WORK: SIGHTS REMOVED ALSO DATE: 1-11-79
SCOPE SCREWS FROM: XX BARGAIN STORE
WHITAKER + TILLEY
ENFIELD N.C.
FIRED AMMO TYPE: UNKNOWN GUN #: 6627846
& CONDITION: — CODE: W-X-8-73
PROOF: PRIPB INSP.: 73 TEST: 111 GA./CAL.: 270
HEADING: OK CHECKED BY: M LADY
BREECH OPENING: OK APPROVED: APL 3/2/79
RECOIL SHOULDERS: OK APPROVED: OK 3/2/79
CHAMBER: OK APPROVED: OK 3/2/79
TEST: — APPROVED: OK 3/2/79
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: WV 3-2-79
SMALL DENTS IN WOOD BOLT SHOULDER WEAR
BRIGHT METAL ON BBL.

COMPLAINT: FIRES WHEN TRIGGER IS RELEASED

INCIDENT: BULLET HOLE THROUGH FLOOR BOARD &
TRANSMISSION OF TRUCK

COMMENTS: Trigger pull adjusted below factory specs.
Trigger adjusting screw appears to have been
adjusted outside factory. No return spring tension
on trigger.