

Mr. Stelk,

Here is my rifle which I wrote
and spoke with you about. The safety in some
way caused the rifle to discharge without pulling
the trigger. The trigger pull was adjusted shortly
after I purchased the gun but has never been a
problem in the past. I hope you can determine what
caused this difficulty. I will anxiously be waiting
to hear from you and appreciate your cooperation
in personally taking care of this problem.

Thanks again.

Edward A. Nicklow

P.O. Box 547

Summersville, WV 26651

Home - (304) 872-⁵⁰⁰²~~5007~~

Work - (304) 872-4037

Rifle Ser. No. A6644129 .270 Cal
Model 700 BDL