

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER
R 93-27796

CUSTOMER ORDER NO.

W/BOTTOM PART OF SCOPE MNTS.

FPS

DATE RECEIVED

12/09/93

DATE OPENED

12/16/93

DATE CODE

DT 9-70

SERIAL NUMBER

6371783

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

ADL

ACCESSORIES

W/STUDS

W/SWIVELS

SCOPE BASE

FROM:

MUNLEY, JOHN
5801 RHODES AVE
NEW ORLEANS

LA 70131

SHIP TO:

MUNLEY, JOHN
5801 RHODES AVE
NEW ORLEANSLA
70131

CUST NO: 008856 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Ref. Mfg 1970. Upon receipt, unable to duplicate customer concern. Examination revealed that the action and trigger assembly, likely D. S. Co. and with Vahman action. Bolt stop. Trigger. Components are not working fully.

COMMENTS

Replace trigger assembly. Also action at 1/2 normal replacement cost, as per the spec.

Do forward 1/8/94

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PART
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV