

RECEIVED

OCT 20 1984

E. F. SIENKIEWICZ

OS1524
October 19, 1984

Remington Arms Company
Safety Department
Bridgeport, CT. 06602

Re: Remington Model 700 LH BDL
SN 6761350

Gentlemen:

I was loading my gun and it went off. I had put 2 cartridges in the clip, pushed the bolt forward, and was pushing the safety on. It was harder than normal, and about that time the gun discharged-nearly killing my hunting partner.


Have you had any other reports of this nature with the 700 BDL discharging accidentally? By the way, this gun will only take 2 shells or cartridges in the clip.

I purchased this weapon new in Ogden, Utah and it has not been fired over thirty times. It has never been dropped and has a Redfield scope on it.

Please advise for disposition of this weapon for repair. This is a very serious matter and I expect a rapid response.

Thank you in advance for a prompt reply.

Sincerely,


Robert B. Parker
12207 Ponca Road
Omaha, NE 68112