

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL J.J.M.		CUSTOMER ORDER NO.		<i>potter</i>		R 93-13313	
DATE RECEIVED 06/08/93		DATE OPENED 06/09/93					
DATE CODE		SERIAL NUMBER A6388336		NEW SERIAL NUMBER		MODEL AND GRADE 700 22-250 ADL	
ACCESSORIES		SCOPE BASE		L/SIGHTS		XI 12-76 2ND TII	
FROM: <i>Stuffed</i> PEKIN GUN & SPTG GOODS DON BARTH 1304 DERBY ST PEKIN IL 61554				SHIP TO: PEKIN GUN & SPTG GOODS DON BARTH 1304 DERBY ST PEKIN IL 61554			
L				CUST NO: 001254 C.D.D.L			
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE ☐		PROM. DATE	
						ESTIMATED 7-8-93	
						VIA UPS	
GUN CONDITION						REPAIR CHARGE <i>22</i>	
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT <i>Unable to duplicate Customer Concern. However, inspection revealed that all 3 trigger adjustment screws have had the screws removed. The adjustment stop and trigger screws have been backed out, indicating that the adjustment screws were tampered with. Rep'd mfg 1976.</i>							
PARTS				COMMENTS			
<i>Trigger Pul. 4 1/4 lbs Screw left .006</i>				<i>Replace trigger assembly completely and clear action at normal op. no gas for good work go ahead</i>			
REPAIRMAN <i>R.B.S.</i>				PROOF ☒			
GALLERY TESTER				CLEAN ☒			
DATE				TEST ☒			
DATE				TARGET ☒			
DATE				PATTER ☒			

OFFICE COPY

RD6925 REV. 1