

REM 27830 220GR	100									
REM UMC 23899 150GR	100									
REM 29178 165GR	100									
FED 3006B 180GR	100									
FED P3006Q 165GR	100						1			
FED P3006G 150GR	100					1				1
WIN SHV30064 180GR	100									
WIN SBST3006A 168GR	100									2
WIN S3006XB 150GR	100		2							
TOTAL	1000		2			1	3			3
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN MAG BOX	MISFIRE	BOLT CAME OUT	
B-14	REM 27828 180GR	100					2			
	REM 27830 220GR	100								
	REM UMC 23899 150GR	100								
	REM 29178 165GR	100								
	FED 3006B 180GR	100								
	FED P3006Q 165GR	100					1			
	FED P3006G 150GR	100	1							
	WIN SHV30064 180GR	100	1	1						
	WIN SBST3006A 168GR	100								
	WIN S3006XB 150GR	100								
TOTAL	1000		2	1			3			
NOTE: BOLT HANDEL BROKE OFF AFTER 1000 RD ENDURANCE WHILE TAKING HEAD SPACE										
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN MAG BOX	MISFIRE	BOLT CAME OUT	
B-15	REM 27828 180GR	100	1				2			
	REM 27830 220GR	100	1							
	REM UMC 23899 150GR	100	1							

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060006018

ETE00003008