

REMINGTON ARMS COMPANY, INC. EST. 1816 **Remington.**

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

PLEASE MAIL
REMITTANCE
TO BOX CHECKED

BRIDGEPORT, CONN. 06602

☒ ILION, N. Y. 13357

SENT
TO

False River Sports Shop, Inc.
211 W. Main St.
New Roads LA 70760

INVOICE NO **R-88-05101**

INVOICE DATE

SHIP TO

APR 22 1988

JPLA

OUR ORDER NO **R-88-05101-700**

OUR ORDER NO

SHIP VIA **UPS**
DO 9-86

700 TMR MAG. BDL B6735295
W/studs, L/sights

COMPLAINT: When I pushed the safety forward, the rifle went off.
MAIN FAULT: Trigger assem. is full of rust & paint-assem. is so full of rust & paint that the trigger will not consistently return under sear-safety cam on cocking. Rifle has been very poorly maintained.

1. 26345 Trigger assem. R.O.C.
2. Polished chamber
3. Test

QUOTATION
TO REMINGTON ARMS CO., INC.

RECEIVED
MAY 05 1988
Ar...

TOTAL REPAIR CHARGE	40.00
INSURANCE	
PARCEL POST	
UPS	4.09
TOTAL CHARGES	44.09

44.09

THE ITEM ABOVE HAS BEEN RECEIVED AND IS BEING REPAIRED.
SHIPMENT WILL BE MADE APPROXIMATELY

THIS IS AN ESTIMATE TO REPAIR OR REPLACE THE ITEMS LISTED ABOVE. TO SATISFY YOURS, PLEASE APPROVE BY SIGNING BELOW. RETURN: 1st COPY

TO REMINGTON ARMS CO., INC., ILION, N. Y. RETAIN SECOND COPY AS YOUR RECEIPT. REPAIR TO 1st COPY **4-6 weeks.**

AFTER RECEIPT OF APPROVAL

CUSTOMERS SIGNATURE *Christopher T. Dineen*

Please Trip gun

NOTE: IF YOU DESIRE ANY CHANGE IN SHIPMENT, PLEASE ADVISE US IMMEDIATELY.

FOR COMPUTER REF. ONLY

JUN 3 1988

CLEAN, TEST, TARGET

REPAIRMAN *[Signature]*