

Warranty. I don't want any replaced parts or new trigger groups. I want a new rifle. I'm 30 years old & I have been hunting all my life with Remington rifles. I never had an experience like I had that day. I love my new model 700 BDL 1 m. m mag. But I will not accept the same rifle under any conditions because I could never hunt or trust the same rifle again. I had to remove my scope from the rifle. It was mounted by a gunsmith with lock tight because it was a magnum rifle, and two of the scope mount screws had to be drilled out. I will not accept responsibility for the screws, because if the rifle would not have broke the mounts,  it would have never had to come off. I am included a receipt from the person that ordered it.

CHECK
INC. OR N.O. Remington.
REPAIR

NO. R-88-05101

DATE

SHIP TO

JPLA

APR 22 1988

86

is rifle went

int-assem.
I not consistently
as been very

05 1988

REPAIR CHARGE 40.00

INSURANCE

PARCEL POST

UPS

4.09

TOTAL CHARGES 44.09

44.09

CUSTOMERS SIGNATURE

4-6 weeks.

Christopher T. Kucera

Please Fax you

CLEAN DEN

REPAIRMAN

ROMA23 REV. 3.84