

Sir,

In the past I've owned several Remington products; from shotguns to Magnum Rifles, and had nothing but the best of service out of all firearms, except the latest Rifle, 700 Custom Safari 8 mm Rem. Mag. I purchased the Rifle ^{NEW} from Holiday Sports goods in Deland, N.C. And found that: 1. Scope mount holes out of line; Had to buy a set of Redfield windage adj. scope mounts to correct the problem; And still could not get the Scope Recticle in line with the center of the barrel bore. 2. Barrel Bore Pitting - Deteriating with less than 2 boxes of Ammo fired through the Rifle. 3. Misadjusted trigger mechanism; Slack then fire 4. Faulty Safety; real hard to operate & sometimes won't, which caused an accidental shooting one of my best friends foot; which has been a burden to both of us along with his family. I paid more for this Rifle than I've ever spent before and had more problems with it; It figures don't it. - OVER -