Remington.

REMINGTON ARMS COMPANY, INC.

SPART-STEEL ARDY WEN, NOILLI

TELEPHONE (315) 894-9961

٦

Mr. Robert Reimer 249 Main St. Slatington, PA 18080 February 18, 1988

Repair Order R-88-00009-700 Bolt Only

Dear Mr. Reimer:

We recently received the above subject Model 700 bolt only covered by your correspondence of recent date.

Unfortunately, in order to complete the necessary repairs, it is essential that the balance of the arm be returned. This type of bolt should not be exchanged with another gun, because they are headspaced to fit that certain gun.

When effecting its return, please tag with your name, address, and refer to this letter and the above subject repair order number for identification.

Cordially,

I. Valent

D. Valent Arms Service Division

DV:cm